
(((echometer)))

PRT 2234 06/16/2011 09:19:52AM







Comments and Recommendations

On 50% timer. Well made a stuffing box leak yesterday and is experiencing severe Cycling Gas Interference w/ 35-75% effective Fillage.

Downhole Diagnostic Shawn Dawsey shawn@DownholeDiagnostic.com www.DownholeDiagnostic.com

(((ECHOMETER))) Windham 42-3 06/16/2011 09:26:16AM Downhole Diagnostic Fluid Above Pump 3345 ft **Liquid Level** 5085 ft **Equivalent Gas Free Above Pump** 2867 ft Production Gun Date Entered 01/01/11 Sec Current Potential BBL/D Oil 4 12 Water BBL/D Gas 4.0 Mscf/D **IPR Method** Producing Efficiency





Comments and Recommendations

On 50% timer. 500# shot. Notice: 2867' of GFLAP! This well has a tapped Bull Plug on bottom of the Mud Anchor (defeating the DH Gas Separation design).

Downhole Diagnostic Shawn Dawsey shawn@DownholeDiagnostic.com www.DownholeDiagnostic.com