
(((echometer)))

HT HLT002 06/07/1995 11:24:00AM






Comments and Recommendations

Running 100% on POC/VFD. Well was pulled 1-month ago for Tubing Leak and it appears the TAC was not properly set: card slanted to Tubing Spring Constant.

Downhole Diagnostic Shawn Dawsey shawn@DownholeDiagnostic.com www.DownholeDiagnostic.com

(((ECHOMETER))) Anchorman #1 06/07/1995 11:13:31AM Downhole Diagnostic 3136 ft Fluid Above Pump **Liquid Level** 3793 ft Equivalent Gas Free Above Pump



Running on 100% POC/VFD. 600# shot.

Shawn Dawsey shawn@DownholeDiagnostic.com www.DownholeDiagnostic.com

945 ft